

State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

| Representatives Present During the Inspection: | | | | | | |
|--|---------------------------------------|--|--|--|--|--|
| OGM | Pete Hess Environmental Scientist III | | | | | |
| Company | Jay Marshall Resident Agent | | | | | |

Z

Inspection Report

| Permit Number: | C0070013 | | |
|------------------|--------------------------|--|--|
| Inspection Type: | PARTIAL | | |
| Inspection Date: | Thursday, March 19, 2009 | | |
| Start Date/Time: | 3/19/2009 12:57:00 PM | | |
| End Date/Time: | 3/19/2009 2:45:00 PM | | |
| Last Inspection: | Thursday, March 05, 2009 | | |

Inspector: Pete Hess, Environmental Scientist III

Weather: Sunny; 50's F.

InspectionID Report Number: 1952

Accepted by: jhelfric

3/24/2009

Permitee: UTAHAMERICAN ENERGY INC Operator: UTAHAMERICAN ENERGY INC

Site: HORSE CANYON MINE

Address: PO BOX 986, PRICE UT 84501

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

| Total Permitted | 5,992.07 |
|------------------------|----------|
| Total Disturbed | 99.56 |
| Phase I | 61.65 |
| Phase II | |
| Phase III | |

Mineral Ownership

✓ Federal✓ State✓ County

☐ Other

Types of Operations

✓ Underground

☐ Surface ☐ Loadout

☐ Processing☐ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Pete Hess, Environmental Scientist III
Inspector ID Number: 46

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801 telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

Date

Monday, March 23, 2009

Permit Number: C0070013 Inspection Type: PARTIAL

Inspection Date: Thursday, March 19, 2009

Page 2 of 4

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

| | | Evaluated | Not Applicable | Comment | Enforcement |
|------|---|-----------|----------------|----------|-------------|
| 1. | Permits, Change, Transfer, Renewal, Sale | | | | |
| 2. | Signs and Markers | V | | | |
| 3. | Topsoil | ✓ | | V | |
| 4.a | Hydrologic Balance: Diversions | ✓ | | ✓ | |
| 4.b | Hydrologic Balance: Sediment Ponds and Impoundments | ✓ | | ✓ | |
| 4.c | Hydrologic Balance: Other Sediment Control Measures | ✓ | | | |
| 4.d | Hydrologic Balance: Water Monitoring | ✓ | | ✓ | |
| 4.e | Hydrologic Balance: Effluent Limitations | ✓ | | ✓ | |
| 5. | Explosives | ✓ | | ✓ | |
| 6. | Disposal of Excess Spoil, Fills, Benches | | | | |
| 7. | Coal Mine Waste, Refuse Piles, Impoundments | ✓ | | | |
| 8. | Noncoal Waste | ✓ | | | |
| 9. | Protection of Fish, Wildlife and Related Environmental Issues | ✓ | | ✓ | |
| 10. | Slides and Other Damage | ✓ | | | |
| 11. | Contemporaneous Reclamation | | | | |
| 12. | Backfilling And Grading | | | | |
| 13. | Revegetation | | | | |
| 14. | Subsidence Control | | ✓ | | |
| 15. | Cessation of Operations | | ✓ | | |
| 16.a | Roads: Construction, Maintenance, Surfacing | ✓ | | ✓ | |
| 16.Ł | Roads: Drainage Controls | V | | | |
| 17. | Other Transportation Facilities | | | | |
| 18. | Support Facilities, Utility Installations | V | | ✓ | |
| 19. | AVS Check | | | | |
| 20. | Air Quality Permit | V | | | |
| 21. | Bonding and Insurance | ✓ | | V | ✓ |
| 22. | Other | | | | |

Permit Number: C0070013
Inspection Type: PARTIAL

Inspection Date: Thursday, March 19, 2009

Page 3 of 4

3. Topsoil

The Permittee's contractor continues to add topsoil volume to the storage pile area. The Permittee intends to sample the rock tunnel development waste in accordance with the requirement in the MRP in the very near future. Muck was being extracted from the #1 entry this day; the material appears to be mostly beige sandstone material. The Permittee must analyze for acid and toxic potential, (Appendix 5-7, Refuse Testing) of this coal mine waste.

4.a Hydrologic Balance: Diversions

The Permittee's contractor was stripping topsoil in order to construct a diversion from the base of the coal stockpile pad to the ditch north of the topsoil stockpile (this ditch reports into the #1 or main pond).

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The Permittee recently had the Mine site drainage control evaluated by a hydrologist from EarthFax Engineering. It was determined that the incisement which has been constructed for the pond adjacent to where the truck loading loop will be constructed is not large enough to handle the volume of water which will report to it. This pond is being re-evaluated by the Permittee and EarthFax.

4.d Hydrologic Balance: Water Monitoring

Mr. Marshall conducted the first quarter of 2009 surface water monitoring requirements for the Lila Canyon Mine site during today's inspection. The following sites were noted as dry; L1S (main fork Lila Creek), L2S, (right fork above Mine), and L3S (right fork below Mine pond). Crest gauge and siphon sampler #1 (Main fork of Lila below County road #126) noted that the last documentable event was a snow fall in October 2008. No other flows were measured.

4.e Hydrologic Balance: Effluent Limitations

The two permitted UPDES outfalls for this site, (L4G / sediment pond discharge) and L5G / Mine water discharge has yet to be constructed. Mr. Marshall stated that the 60 inch culvert for the sediment pond undisturbed bypass should arrive on site either 3/20 or 3/23.

5. Explosives

All three of the rock tunnels have been advanced to a depth of at least 50 feet; the Permittee is now using 225 pounds of explosive per 9 foot drill round (full face). The Permittee has relocated the dynamite and detonator storage magazines from the shop/warehouse pad to the water treatment plant pad.

9. Protection of Fish, Wildlife and Related Environmental Issues

There were no birds observed in flight over the Mine site this day.

Permit Number: C0070013 Inspection Type: PARTIAL

Inspection Date: Thursday, March 19, 2009

Page 4 of 4

16.a Roads: Construction, Maintenance, Surfacing

The Permittee recently met with the Emery County road department concerning the section of EC 126 connecting Lila Canyon with US 50 and 6.

18. Support Facilities, Utility Installations

The Lila site is receiving AC power from Rocky Mountain Power, via the temporary power cable.

21. Bonding and Insurance

A notice of violation was issued to the Permittee on March 17, 2009 for failure to maintain bond coverage with a surety having a minimum A.M. Best rating of A- for the permit area "A" bond. The Permittee intends to correct this on March 23, 2009.